



COLLEGE OF ENGINEERING PUNE
(An Autonomous Institute of Govt. of Maharashtra)

Dr. Ishwar P. Sonar

Associate Professor,
Applied Mechanics Division,
Civil Engineering Department,
College of Engineering Pune
Shivajinagar, Pune – 411005
Mobile No: 9890272905

Email : ips.civil@coep.ac.in

Office : 025507046

No. COEP/Civil/Cons/ips/2020/3369/ 2504

Date: 20.7.2021

To,

Mrs. Mrinalini Bhosale
Principal,
Vikhe Patil Foundation's
Vikhe Patil Memorial School, Pune

Sub: Building Safety Certificate for School Building of Vikhe Patil Foundation's Vikhe Patil Memorial School near Patrakar Colony, Pune

Ref: Your letter No. VPMS/2021-22/ Sec/13 dated 8 July, 2021

Respected Madam,


As per reference mentioned above, you have requested for building stability and Safety Certificate in respect of Vikhe Patil Memorial School located near Patrakar Colony, Pune. Accordingly, I visited your school on 14.7.2021 for the visual inspection from the structural point of view, in the presence of Mr. K. M. Nighute, Engineer from Vikhe Patil Foundation. The visual inspections of structural members like beams, columns and slabs are done. The detailed structural drawings and design, previous structural audit report and repairs etc; of the said school building were not made available. However, the building safety certificate from the reputed structural consultant G.A. Bhilare Consultants Pvt. Ltd. Pune, bearing letter No. GABCPL/GAB/MR/ BSC/0081/2020 dated 12.10.2020 and, also a building safety certificate dated 24.05.2021, from Deltacom Structural consultants are received from your side. The said RCC building is consisting of Ground + Three floors. As per the letter from Delatacom Consultants, this building was constructed in 2010-11.

The visual inspections of structural members like beams, columns and slabs are done. The building is well maintained with plaster and colour. No structural damages were observed. The photographs with titles are also attached herewith. Fire fighting system was also provided. From the visual inspection, it is concluded that the building is stable up to date. The building is found structurally safe and fit for the use for the educational purpose, as a school building. This certificate is valid for the one year only.

Thanking you.

Yours faithfully,

Dr. I. P. Sonar


20/7/2021
Dr. Ishwar P. Sonar
Associate Professor
Civil Engineering Deptt.
College of Engineering, Pune-5